Thoroughly read and understand ICC Software update instructions prior to rework.

ICC UPDATE - PROCEDURE



IMPORTANT - Read before carrying out repairs: During the USB installation procedure the USB stick "**must not**" be removed until the process is complete. Removal of the USB stick prior to completion will lock the ICC unit, and render the ICC unusable. Pay special attention to further warnings contained within the procedure document.

Important - How to install software onto USB

Instruction available on PTS under Toolbox-Upgrade/Mods


- Update the IDS to the latest level, 83.01 or later (if necessary)
- 2. Connect an external power supply to the vehicles battery and to the IDS.


Note: It is very important that the ICC and the IDS have full power available at all times during the ICC software upgrade process.




- 3. Turn off and disconnect all accessories on the ICC.
 - a) Audio
 - b) Climate control
 - c) Aux (I-pods, I-phones)
 - d) Bluetooth Un-bond all paired devices
 - e) Remove any attached USB hardware










13. If the vehicles battery voltage is low or the ignition is switched off when the upload of the software has begun, then possible ICC Failure may occur.

WARNING: To prevent ICC failure, connect an external power supply to the vehicles battery and to the IDS.

Then select the "Tick".



14. It may be necessary to inform others of the ICC update currently in progress.


Dealers should create and/or print off a sign such the one to the right, to display on the vehicle during the ICC update procedure.


CAUTION


ICC UPDATE IN PROGRESS


Do **NOT** turn the ignition **OFF** or disconnect the battery charger from this vehicle.


15. Turn the ignition ON, and then select the "Tick".












Then, select the "Tick".


26. The IDS will check the USB port and the USB stick, if NO faults are noted, then select the "Tick".



27. Depending on the vehicle level, it will take between 5 to 30 minutes for the software update to be completed

5 to 10 minutes for a TX, 15 to 20 minutes for a TS, 25 to 30 minutes Titanium

Select "confirm" to continue




28. The upload is now in progress. USB will start and stop flashing during this process, this normal.

(Do NOT proceed until the display has completely refreshed. See Step 28 for time indication.)



29. NOTE: Attach a warning sign to the driver's door glass warning others NOT to; remove the USB stick or

turn the ignition OFF. Failure to adhere to this instruction could cause the ICC to be rendered inoperative and require complete replacement. (Ref. Step 15)



30. Once complete, the screen will stay blank for up to 5 minutes.

The ICC will reboot and the screen will turn ON. Titanium vehicles can take longer to reappear.

Do <u>NOT</u> remove USB stick at this stage.



31. Once the screen has rebooted, the update includes a Bluetooth update, this will begin automatically.



32. The ICC screen will show the Bluetooth update status in percentage.


NOTE: If the Bluetooth Firmware update does not pass 17%, simply press the retry button on the IDS. This will relaunch the Bluetooth Firmware update.



33. Once the Bluetooth update has completed, the ICC screen should return back to its original screen.



34. Now select "continue".




35. The update has successfully been completed.

Select the "Tick", the ICC screen should blank out for a minute or so then turn back on.

NOW remove USB stick from the vehicle.

Now, perform a CMDTC self-test and clear any CMDTC's logged.



[END]