FORD:

2008-2010 F-Super Duty

This article supersedes TSB **11-6-6** to update the Service Procedure and Service Labor Time Standards.

ISSUE

Some F-Super Duty vehicles equipped with a 6.4L engine may exhibit an external coolant leak from the radiator. Slow leaks at cooling system hoses/connections can lead to low coolant levels. Excessive hot and cold cycling associated with low coolant levels can cause stress within the radiator tubes, possibly resulting in cracks in the tubes.

ACTION

Follow service procedure steps to repair this concern.

SERVICE PROCEDURE

Thermostat inspection is no longer required because IDS release 71.04 and later added a cooling system monitor.

- Inspect for the cooling system venturi tee being installed and verify proper orientation. Refer to Workshop Manual (WSM), Section 303-03, Degas Bottle - 6.4L Diesel.
- 2. Degas bottle port inspection and repair:
 - a. Dual-port design requires the degas bottle to be replaced with the single-port design and a new degas bottle cap. (Figure 1) Proceed to Step 3.



Figure 1 - Article 11-12-4

- b. Single-port design requires inspection of the degas bottle cap sealing surface for nicks and/or cracks. If present, replace the degas bottle and degas bottle cap. Proceed to Step 3.
- 3. Coolant leak inspection and repair:
 - a. Visually inspect all cooling system hoses/connections for evidence of coolant loss such as white coolant residue (dried coolant) or liquid coolant and repair as necessary. (Figures 2 and 3)




Figure 2 - Article 11-12-4

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 11-12-4 (Continued)



Figure 3 - Article 11-12-4

- b. The upper and lower radiator hoses should not be removed to perform a leak inspection. White grease is used on the inside of the hose to aid in assembly and may be mistaken as a leak. A leaking radiator hose connection will be visible on the outside of the hose connection. (Figure 3)
- c. If a leak is found at a radiator hose O-ring seal, the radiator hose should be replaced. The upper and lower radiator hoses have been updated with a dual O-ring seal design for improved sealing. The upper and lower radiator hoses should not be replaced as a pair unless both hoses have confirmed leaks.
- 4. Replace the radiator. Refer to WSM, Section 303-03.
 - a. Be sure to remove the engine coolant block plugs from both sides of the engine to drain the coolant from the engine block.
 - Fill the cooling system with a 50/50 mixture of distilled water and new Motorcraft® Premium Gold Engine Coolant. Do not reuse coolant that was drained from the cooling system.
 - c. Utilize the Rotunda Heavy Duty Airlift II radiator refiller tool (UVU550500INT) or equivalent when filling the cooling system.
 Filling without use of the Heavy Duty Airlift II radiator refiller tool may leave excessive air in the system

PART NUMBER	PART NAME
8C3Z-8009-B 9C3Z-8A080-AA 9C3Z-8101-B AC3Z-8260-A AC3Z-8286-A 8C3Z-8B379-B VC-7-B	Radiator Degas bottle Cap- Degas bottle Upper Radiator hose Lower radiator hose Venturi Tee Motorcraft® Premium Gold Engine Coolant

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage IMPORTANT: Warranty/ESP coverage limits/policies are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

OPERATION 111204A	DESCRIPTION 2008-2010 F-Super Duty 6.4L: Inspect The Cooling System, Correct Or Install Venturi Tee, Replace The Radiator, Includes Time To Drain And Fill The Cooling System (Do Not Use With Any Other Labor Operations)	TIME 2.8 Hrs.
111204B	2008-2010 F-Super Duty 6.4L: Inspect The Cooling System, Correct Or Install The Venturi Tee, Replace The Degas Bottle And Cap If Necessary, Replace The Radiator, Includes Time To Drain And Fill The Cooling System (Do Not Use With Any Other Labor Operations)	3.2 Hrs.
111204C	2008-2010 F-Super Duty 6.4L: Inspect The Cooling System, Correct Or Install Venturi Tee, Replace The Upper And/Or Lower Radiator Hose(s), Replace The Radiator, Includes Time To Drain And Fill The Cooling System (Do Not Use With Any Other Labor Operations)	2.9 Hrs.

TSB 11-12-4 (Continued)

Actual

111204D 2008-2010 F-Super Duty 3. 6.4L: Inspect The Cooling System, Correct Or Install The Venturi Tee, Replace The Degas Bottle And Cap If Necessary, Replace The Upper And/Or Lower Radiator Hose(s), Replace The Radiator, Includes Time To Drain And Fill The Cooling System (Do Not Use With Any Other Labor Operations)

3.3 Hrs.

MT111204 For Any Additional Cooling System Repairs Use SLTS

System Repairs Use SLTS Time Operations If Available Or Actual Time

DEALER CODING

	CONDITION
BASIC PART NO.	CODE
8009 (OPERATIONS A OR B)	42
8590 (OPERATIONS C OR D)	42