12-VOLT BATTERY DISCHARGED—WILL NOT HOLD CHARGE—RADIO WITH 4.2-INCH DISPLAY ONLY—BUILT ON OR BEFORE 6/21/2013

TSB 13-7-10

FORD:

2013 C-MAX

This article supersedes TSB **13-04-13** to update the Part List/Service procedure and vehicle build date.

ISSUE

Some 2013 C-MAX vehicles equipped with a 4.2 inch display radio only and built on or before 6/21/2013, may exhibit a 12-volt battery that is unable to maintain a charge or becomes discharged.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

- 1. Reboot the scan tool.
- 2. Install a battery charger.
- Reprogram the front control/display interface module (FCDIM) to the latest calibration using IDS release 85.05 or 86.01 and higher. This new calibration is not included in the VCM 2012.9 DVD. Calibration files may also be obtained at www.motorcraft.com.
 - a. Be aware that electrical accessories may operate during programming and should be considered a characteristic.

b. Reset FCDIM display time and date, refer to the Owners Manual, Audio System section.

WARRANTY STATUS: Eligible Under Provisions Of

New Vehicle Limited
Warranty Coverage
Warranty/ESP coverage
limits/policies/prior approvals
are not altered by a TSB.
Warranty/ESP coverage
limits are determined by the
identified causal part and
verified using the OASIS
part coverage tool.

OPERATION DESCRIPTION TIME
130710A 2013 C-MAX: Reprogram 0.4 Hr.

130710A 2013 C-MAX: Reprogram
The FCDIM Includes Time
To Clear Codes After
Repair (Do Not Use With

Any Other Labor Operations)

DEALER CODING

BASIC PART NO. CODE 10D885 04

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.