

EASY ENTRY/EASY EXIT FEATURE—POWER TELESCOPING/TILT STEERING COLUMN DOES NOT RETURN TO CORRECT POSITION

TSB 13-1-1

FORD:

2013 Taurus
2011-2013 F-150
2013 Edge, Explorer, Flex

LINCOLN:

2013 MKS, MKT, MKX

This article supersedes TSB **12-11-10** to update the vehicle model years, vehicle lines, Issue Statement and Action Statement.

ISSUE

Some 2011-2013 F-150, 2013 Edge, Explorer, Flex, Taurus, MKS, MKT and MKX vehicles equipped with Easy Entry/Easy Exit feature may exhibit the power telescoping/tilt steering column not returning to the correct position (customer set point) when the feature is enabled.

ACTION

Reprogram the steering column control module (SCCM) to the latest calibration using IDS release 82.01 and higher. This new calibration is not included in the VCM 2012.11 DVD. Calibration files may also be obtained at www.motorcraft.com.

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB.
Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

OPERATION	DESCRIPTION	TIME
130101A	Reprogram The SCCM, Includes Time To Clear Codes After Repair (Do Not Use With Any Other Labor Operations)	0.2 Hr.
DEALER CODING		
BASIC PART NO.		CONDITION CODE
3F791		04

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.