

VEHICLE SHIFTS TO PARK BELOW 8 KM/H (5 MPH) AND/OR WRENCH LIGHT WITH DTC P081F

TSB 13-9-10

LINCOLN:
2013-2014 MKZ

ISSUE

Some 2013-2014 Lincoln MKZ vehicles may shift to park when the vehicle is traveling below 8 Km/h (5 MPH) and/or may exhibit a wrench light illuminated with diagnostic trouble code (DTC) P081F stored in the gear shift module (GSM).

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

Reprogram the powertrain control module (PCM) and the gear shift module (GSM) to the latest calibration using IDS release 86.03 and higher. Calibration files may also be obtained at www.motorcraft.com.

The push button shift transmission has unique operating characteristics including an automatic return to park feature. Please refer the customer to the Owner's Manual, transmission section for expected system operation.

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB.
Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

OPERATION

130910A

DESCRIPTION

2013-2014 MKZ:
Reprogram The Appropriate Modules As Required By The Software Update Includes Time To Clear Codes After Repair (Do Not Use With Any Other Labor Operations)

TIME

0.4 Hr.

DEALER CODING

BASIC PART NO.
7D443

CONDITION
CODE
42

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.