

DIRT ACCUMULATION ON REAR DOOR SCUFF PLATES

TSB 12-9-2

FORD:

2010-2013 Taurus

The article supersedes TSB 11-11-20 to update the vehicle model years and the Part List.

ISSUE

Some 2010-2013 Taurus vehicles may exhibit road dust accumulation on the rear door scuff plate area.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

1. Paint the replacement body quarter trim panel from the Dust Kit to match the vehicle exterior color.
2. Install the Dust Kit parts. Refer to instruction sheet included in the kit.

PART NUMBER	PART NAME
AG1Z-5420530-DB	Dust Kit

OPERATION	DESCRIPTION	TIME
120902A	2010-2013 Taurus: Install The Revised Weatherstrip Kit Following The Kit Instructions. Can Be Claimed With Operations B And C As Necessary	2.8 Hrs.
120902B	2010-2013 Taurus: Additional Time To Prep and Paint New Moulding Assemblies. Can Be Claimed With Operations A And C	1.5 Hrs.
120902C	2010-2013 Taurus: Additional Time For Vehicles With Tri-Coat Finish. Can Be Claimed With Operation A And B	0.5 Hr.

DEALER CODING

BASIC PART NO.
5420530

CONDITION
CODE
42

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB.
Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.