

VCI Software 1.0.1.21

The VCI Manager 1.0.1.21 update focuses on stabilizing wireless and Point-to-Point (P2P) network connections (particularly resolving a compatibility issue introduced by a Windows 11 security update), polishing the VCI Manager user interface (UI) for better alignment and visibility across different screen resolutions, and updating help documentation alongside key language translations.

Networking / Wi-Fi

Fixed Wi-Fi settings reverting to P2P mode after recovery or update.

Fixed Wi-Fi channel scan reporting two different default values.

Fixed Windows 11 Security Update (KB5072033) causing P2P connection failures.

UI / UX

Fixed VCI Manager splash screen text and graphic content not centered.

Fixed VCI Manager UI text being cut off in the Network Setup tab.

Fixed inconsistent VCI Interface Type text displayed beneath the VCI icon.

Fixed VCI icon interface text incorrectly showing "Access Point" when Ethernet and Wireless are disabled.

Fixed Network Setup icon rendering too far down on low-resolution screens.

Help & Documentation

Corrected Wi-Fi setup help text to display instructions for all 3 connection modes.

Fixed formatting of help files.

Fixed translations for Bulgarian, Polish, and Greek.

Note :

There is a current know issue around using VCMM and the VCMM Instrumentation in Datalogger with the VCMM Wireless. This is currently being investigated. If functionality for the VCMM Instrumentation is needed in Datalogger users must connect wired for the tool to function properly.

